

8" SANDERS

VERTICAL OR HORIZONTAL FOR ABRASIVE MACHINING WET OR DRY


- 8" x 60" belt.
- 7-1/2 HP, 3 PH motor.
- Twin belt drive.
- Replaceable platen.
- Cast iron table 8" x 12".
- Platen working surface 8" x 13".
- Dimensions — L 25" x W 25" x H 62".



MODEL S8W

Air tensioning on belt, 40 to 50 lbs. of shop air. Air gauge and valve included.

HEAVY-DUTY



MODEL S8HD

MODEL S8D 8" VERTICAL SANDER, DRY. 7-1/2 HP, 3 PH motor. Magnetic switch with jog button. 1725 RPM, 3500 SFPM. Wt. 645 lbs.

MODEL S8W 8" VERTICAL SANDER, WET. 7-1/2 HP, 3 PH motor. Magnetic switch with jog button. Heavy-duty coolant pump with switch. Wt. 760 lbs.

MODEL S8HD 8" HORIZONTAL SANDER, DRY. 7-1/2 HP, 3 PH motor. Magnetic switch with jog button. Wt. 900 lbs.

MODEL S8HW 8" HORIZONTAL SANDER, WET. 7-1/2 HP, 3 PH motor. Same as above but with 10 gal. coolant pump with tank.

10" BELT SANDERS



**AVAILABLE
AS
VERTICAL
OR
HORIZONTAL**

**10 HP
RUGGED!**

MODEL S10D

- 10" x 90" belt.
- 3400 SFPM.
- Steel platen 29" x 10".
- Work surface 28" x 10".
- Cast iron table 14" x 18".
- Table tilt 45° down, 15° up.
- Air tension on belt.
- 10 HP, 3 PH, TEFC.
- Mag controls with jog.
- Dimensions — L 39" x W 28" x H 70".

MODEL S10D 10" VERTICAL SANDER, DRY. 10 HP, 3 PH motor. Magnetic switch with jog button. 1725 RPM, 3500 SFPM. Wt. 1160 lbs.

MODEL S10W 10" VERTICAL SANDER, WET. 10 HP, 3 PH motor. Same as above but with built-in coolant system. Wt. 1550 lbs.

MODEL S10HD 10" HORIZONTAL SANDER, DRY. 10 HP, 3 PH motor. Wt. 780 lbs.

MODEL S10HW 10" HORIZONTAL SANDER, WET. 10 HP, 3 PH motor. Same as above only with built-in coolant system. Wt. 895 lbs.